


Sector Long Island Sound MSD Coram





	Projects
103 0 2 0	


LT William Stewart



M/V Catherine Ann



RRT Activation:	No
Type and amount of product spilled:	Diesel Fuel 200 Gallons (400 gallon potential)
Cause of spill:	Vessel Fire (Electrical Short)
Time and date of spill:	08 August 2015, 2330
Responsible Party:	Private
Key operational activities:	Initially a federal funded clean up. Contractor oversight.
Major lessons learned:	Swift response strategies ensured minimal damage to the environment. Used OSLTF until insurance assumed liability.
Lead Coordinator:	MSD Coram: MST3 Hill (631) 732-0190





M/V Catherine Ann







T/V Coimbra




RRT Activation:	No
Type and amount of product spilled:	Heavy Fuel Oil (Sheen sizes varied up to 9 miles long)
Cause of spill:	Torpedoed in 1942
Time and date of spill:	Satellite imagery detected suspected oil: 12 JUL, 19AUG, 20AUG, 28AUG
Responsible Party:	None
Key operational activities:	Initial over flight via HC-144. Requested NOAA SSC trajectory support. Monitoring.
Major lessons learned:	NOAA has a database called RULET! Reporting between NOAA and NRC needed better coordination
Lead Coordinator:	MSD Coram: MST2 Mello (631) 732-0190






T/V Coimbra





An oil slick was detected emanating from the torpedoed tanker Coimbra approximately 53 miles southwest of Montauk Point. The slick was 2.9 miles in length and up to 0.3 miles wide. Skies were clear and winds were from the southeast at 5 knots at the time of the image.


Confidence is high that the slick is oil because the Coimbra is a known repeat leak source and portions of the slick appear shimmery in the high resolution imagery.





RULET Vessels along the North East Coastline







S/V Pocho



RRT Activation:	No
Type and amount of product spilled:	No product discharged. Potential of 20 gallons (Diesel).
Cause of spill:	While underway vessel lost propulsion and began taking on water
Time and date of spill:	02 October 2015, 2000
Responsible Party:	Private Owner (South African National)
Key operational activities:	Contractor oversight, Communication with RP
Major lessons learned:	Documentation needed for NFPC to recoup funds from a foreign national with no ties to USA
Lead Coordinator:	MSD Coram: MST3 Kerr (631) 732-090





Sag Harbor Storm Response



RRT Activation:	No	
Type and amount of product spilled:	60 gallons combined for 8 vessels effected	
Cause of spill:	8 vessels broke loose from moorings during storm.	
Time and date of spill:	03 October 2015, 1030	
Responsible Party:	Private Owners	
Key operational activities:	Coordinated with Harbormaster and RP's to salvage all vessels.	
Major lessons learned:	N/A	
Lead Coordinator:	MSD Coram: MST3 Kerr (631) 732-090	





Northport Storm Response



RRT Activation:	No
Type and amount of product spilled:	30 Gallons gasoline
Cause of spill:	Sinking
Time and date of spill:	04 October 2015, 1600
Responsible Party:	Private Owner
Key operational activities:	Coordinated with Harbormaster and RP's to salvage vessel.
Major lessons learned:	N/A
Lead Coordinator:	MSD Coram: PR MST3 Kerr





Sector Long Island Sound



Meetings

Training

Description	Dates	Description	Dates
GRP Rewrite	Ongoing	ICS 300	October 27-30, 2015

Drills/Exercises

National Grid PREP Exercise; Northport, NY	October 14, 2015
Global Commander Notification Drill; Oyster Bay, NY	November 13, 2015
Plum Island PREP Exercise; Plum Island, NY	November 20, 2015
Transportation Security Incident, CG Academy (RRT1) RRT 2	May 5, 2016



Marine Safety Detachment Coram



Contact Info

Sector LIS SCC: (203) 468-4401 (24hr)

MSD Coram: (631) 732-0190

MSD Duty PR: (203) 410-2126 (24hr)

Qualified Unit Responders

FOSC Representatives: 3

Pollution Responders (PR): 8





Questions?



