


HURRICANE FLORENCE ESF-10 RECAP





Emergency Support Function #10



- Mission Assignment: \$10M
- Key Objectives: Assess Coastline and Remove • Oil/HAZMAT from Targets w/ Threat to Environment

NORTH

CAROLINA

RESOURCES COMMISSIO

• Unified Command: USCG, EPA, NC Wildlife Resources Commission, & NC Department of **Environmental Quality**











FEMA Mission Assignment

Statement of Work:

- Removal, mitigation & disposal oversight of: actual/potential oil discharges & releases of HAZMAT, pollutants & contaminants
- Eliminate/lessen immediate threats to 1) lives, public health, or safety or 2) additional damage to property emanating from actual or potential releases/discharges from facilities, vehicles, intermodal containers & vessels

Best Management Practices: NOAA & stakeholder discussions for vessels in environmentally sensitive areas





Results

- <u>Final Cost</u>: \$8.9M
- <u>Completion</u>: 14 Nov 2018 (60 days)
- ESF-10 Mitigation:148 Vessels
- <u>Owner Removed</u>: 118 Vessels
- <u>Remain In Place</u>: 120 Vessels
- <u>Total Assessed</u>: 362 Vessels















Close-Out Binder: Example Vessel

Target Sticker #	County	Latitude	Longitude	Target Status	Sensitive Site
TFN-106	Beaufort	35.53770	-77.06758	Recovery Complete - Leave in Place	Yes - Standard BMPs Apply
Vessel Name	Vessel Type	Vessel Length	Vessel Registration #	Vessel Owner	Vessel Owner Contact
The Classic	Rec VSL	26	NC4882DE	Not Determined	Not Determined



Target Comments: 276202_003. 26-ft Rec vessel aground. 10OCT: Vessel reassessed. 13OCT: Reassessed vessel still in location. No sheen. On shore but no land access, directly across from boat ramp. 27OCT: Revaluation team went on scene to vessel. Contractors went onboard and did not observe any hazardous substances. No further ESF-10 action. Removed 75 gallons of fuel, 3 batteries, and 4 fire extinguishers. Left in location deemed not a hazard to navigation by WRC. BMP's were followed for the duration of the operation.



Lessons Learned

- Excellent Cooperation/Coordination with all Stakeholders
- Operations Completed Ahead of Schedule & Under Budget
- Timely Remediation from Private Property
- Derelict Vessels & Future of Vessels Left in Place State Engagement
- Audio/Visual Challenges at Incident Command Post
- Unified Command: Clearer Roles/Responsibilities
- Consider FEMA Equipment (e.g., Poster Printers, Life Jackets)
- Use Experts FOSCR Authority Transferred to Strike Team CO/XO





Best Practices: Survey123 and ERMA

×	R4 Florence ESF10	Containers and Vessels		
NRC Rep O Yes	ort (Y/N) *	No		
Division I A-3	D		0	2
Zone # e.g. 1 thur 7 3			E	3
Team ID [•] Team 7	*		8	<
Team Age USCG	ency/Organizati	on *	~	2
Team Me	mber Names *		C	3
Target Sti O Yes	cker (Y/N)	No		
_	entified Date * per 25, 2018		\sim 6	3

× R4 Flor	ence ESF10 Containers and Vessels	
Target New or R New	Revisited *	
Target Location 225 Grandview		8
Target Location (Only select when ap O Canal	51	
Target Location	*	
34.518°N 77.372°W	,	¢
© Esri contribu	utors	Contraction of the second
Target Location	City	
Sneads Ferry		8
Target Location North Carolina		
Target Location	County *	
Onslow		\times \vee





Path Forward

- Leverage Area Committee
 - Derelict Vessel Subcommittee
 - Geographic Response Strategy Subcommittee
- Update Area Contingency Plan
 - Add ESF-10 & Severe Weather Sections
 - Outline Roles/Responsibilities for Unified Command
 - Validate GRSs Sector-wide by Oct 19





