




USCG Marine Safety Detachment Coram

June 2022 to June 2023



Presented by: MST1 Morgan A. Gambino, FOSC-R





Overview

- Hurricane Season Preparedness
- Area Committee Updates
- All cases from June 2022 to June 2023
- Significant Cases in the AOR
 - ❖ 05 AUG 2022 – Hendrickson Car Care Center Fire
 - ❖ 17 MAR 2023 – Aircraft Emergency Landing
 - ❖ 15 MAY 2023 – M/V SCROD II
- Long Island GIUE
- MSD Coram's Pollution Response Team
- Sector LIS and MSD Coram Contacts





Hurricane Season 23:



Lessons Learned:

- Need the plain-language definitions for state and county EOC operating and activation status.
- Compose/maintain an active duty, reserve, and civilian IMT assignment list for Type-3 Events/Incidents.

Best Practices:

- Ensure PORT CONDITION status changes are *officially* received **and acknowledged** by all state and county EOCs prior to the Storm.
- Establish a briefing battle rhythm early; share schedule, phone number(s), and passcode(s) with state and county EOCs via LNOs.
- Know physical location of USCG LNOs (assigned to state and county EOCs) at all times.





Area Committee Updates

- Long Island Sound Area Committee Executive Steering Team Meeting – January 2022
- Area Committee Meeting – April 2022
 - Area Contingency Plan Update – Signed June 23
 - Salvage Response Plan Update – Signed April 23
- ACP updates published on Homeport





Cases: June 2022 to June 2023

- Estimated total actual discharges/releases = 110 gallons
- Letters of Warning = 16
- Notices of Violation = 0
- Federalized Cases = 0





Hendrickson Car Care Center Fire



Date of Spill: 05 AUG 2022

Location of Spill: Halesite, NY

Type and Amount of Product Spilled:
Unknown amount of mixed oils/hazmat

Cause of Spill: Business Fire

Other Agency Involvement:
NYSDEC, Halesite Fire, Huntington Fire,
Greenlawn Fire, Commack Fire, &
Melville Fire

Concerns: Mixed oils discharged, and
chemicals released into Huntington
Harbor





Aircraft Emergency Landing



Date of Spill: 17 MAR 2023

Location of Spill: Shoreham, NY

Type and Amount of Product Spilled:
70 gallons of aviation fuel (potential)

Cause of Spill: Equipment Failure

Other Agency Involvement:
NYSDEC, Suffolk PD, Suffolk Marine Patrol

Concerns: Discharge of aviation fuel into the Long Island Sound





Dredger SCROD II



Date of Spill: 15 MAY 2023

Location of Spill: Bayshore, NY



Type and Amount of Product Spilled:

500 Gallons of bilge oil (potential)

Cause of Spill: Equipment Failure

Other Agency Involvement:
NYSDEC

Concerns: Discharge of mixed bilge oil into the Great South Bay





Long Island GIUE



- **September 2023**
 - Upcoming at National Grid, Northport, NY
 - Average Most Probable Discharge Exercise
 - More information and official invitation to follow





MSD Coram Pollution Response Team



Total MSD Personnel	
Active Duty	13
Civilian	3
Reserve	4
Total Pollution Responders	
Qualified	13
Break-in	1
Total FOSCRs	
Qualified	1
Alternate qualified	0
Break-in	3





Questions/Comments/Concerns?

MSD Coram Office Line: (631) 732-0190
Pollution Responder Duty Cell: (631) 416-0197
Email: USCGMSDCoram@uscg.mil

CAPT Elisa Garrity
USCG Sector Long Island Sound Commander

CDR Nicholas Lajoie
Sector LIS Response Department Head
Duty Cell 203-410-5007

LCDR David Vihonski
Sector LIS Incident Management Division Chief
Duty Cell 203-668-4550

LT Pablo Ortiz
Marine Safety Detachment Coram Supervisor
Duty Cell: 860-857-4364

