




WAPA-KRUM BAY SUBSURFACE OIL INVESTIGATION

US EPA

JANUARY, 2017



15 - 670 0



 Approximate location where diesel emanated in 1992

 Fill area

 Area diesel observed

 Initial area of concern for WAPA















In-Situ Inc.
www.in-situ.com
Rugged Interface Meter
































Highway 30

